

Fig.



Fig.2**Fig.3**


Fig.4




Fig.5**Fig.6**


Fig.7**Fig.8**

A curved arrow labeled '114' points from the 'DESCRIPTION' column of the table below to the 'CONTROL IDENTIFICATION HIERARCHY NUMBER Nc' row.

DESCRIPTION	SETTING
CONTROL IDENTIFICATION HIERARCHY NUMBER Nc	4
CONTROL CATEGORY IDENTIFIER C-ID ₁	1
CONTROL CATEGORY IDENTIFIER C-ID ₂	3
CONTROL CATEGORY IDENTIFIER C-ID ₃	2
CONTROL CATEGORY IDENTIFIER C-ID ₄	0

Fig.9

DEVICE ID	D-ID ₁	D-ID ₂	D-ID ₃	D-ID ₄
ID SETTING	1 : PRINTER	1 : ELECTROPHOTOGRAPHIC	1 : CO. A	1 : AAA
		2 : SUBLIMATION	2 : CO. B	2 : BBB
		3 : INK JET	3 : CO. C	3 : CCC
	2 : MONITOR	1 : CRT	1 : CO. A	1 : AAA
		2 : TRANSMISSIVE LCD	2 : CO. B	2 : BBB
		3 : REFLECTIVE LCD	3 : CO. C	3 : CCC
	3 : PROJECTOR	1 : LCD	1 : CO. A	1 : AAA
		2 : DLP	2 : CO. B	2 : BBB

Fig.10

 115

CONTROL PARAMETER	SETTING
GAMMA CORRECTION VALUE	2. 2
TARGET COLOR SPACE	NTSC
sRGB NEGATIVE VALUE TREATMENT	1 (VALID)
SHADOW	5
HIGHLIGHT	2
CONTRAST	0
BRIGHTNESS	4
RGB COLOR BALANCE	R0/G-1/B2
CHROMATICITY	0
SHARPNESS	THRESHOLD VALUE 2, APPLIED LEVEL 3
STORED COLOR CORRECTION	GREEN 0,0,0 (UNASSIGNED) SAPCE 0,0,0 (UNASSIGNED) SKIN 0,0,0 (UNASSIGNED) RED 0,0,0 (UNASSIGNED)
AUTO ADJUST	5
PAPER	3(PHOTOGRAPHIC PAPER)
RESOLUTION	4(PHOTOGRAPH)
PRINTING DIRECTION	1(ON)


Fig.11


Fig.12


Fig.13

Fig.14

DESCRIPTION	SETTING
DEVICE IDENTIFICATION HIERARCHY NUMBER Nd	4
DEVICE CATEGORY IDENTIFIER D-ID ₁	1
DEVICE CATEGORY IDENTIFIER D-ID ₂	3
DEVICE CATEGORY IDENTIFIER D-ID ₃	2
DEVICE CATEGORY IDENTIFIER D-ID ₄	0


Fig.15

Fig.16

$$\begin{pmatrix} R \\ G \\ B \end{pmatrix} = \mathbf{S} \begin{pmatrix} Y \\ Cb - 128 \\ Cr - 128 \end{pmatrix}$$

$$\mathbf{S} = \begin{pmatrix} 1 & 0 & 1.40200 \\ 1 & -0.34414 & -0.71414 \\ 1 & 1.77200 & 0 \end{pmatrix}$$

Fig.17

$$\begin{pmatrix} X \\ Y \\ Z \end{pmatrix} = \mathbf{M} \begin{pmatrix} Rt' \\ Gt' \\ Bt' \end{pmatrix} \quad \mathbf{M} = \begin{pmatrix} 0.6067 & 0.1736 & 0.2001 \\ 0.2988 & 0.5868 & 0.1144 \\ 0 & 0.0661 & 1.1150 \end{pmatrix}$$

$Rt, Gt, Bt \geq 0$

$$Rt' = \left(\frac{Rt}{255} \right)^r \quad Gt' = \left(\frac{Gt}{255} \right)^r \quad Bt' = \left(\frac{Bt}{255} \right)^r$$

$Rt, Gt, Bt < 0$

$$Rt' = -\left(\frac{-Rt}{255} \right)^r \quad Gt' = -\left(\frac{-Gt}{255} \right)^r \quad Bt' = -\left(\frac{-Bt}{255} \right)^r$$

Fig.18

$$\begin{pmatrix} R_w \\ G_w \\ B_w \end{pmatrix} = \mathbf{N}^{-1} \begin{pmatrix} X \\ Y \\ Z \end{pmatrix}$$

$$\mathbf{N}^{-1} = \begin{pmatrix} 3.30572 & -1.77561 & 0.73649 \\ -1.04911 & 2.1694 & -1.4797 \\ 0.0658289 & -0.241078 & 1.24898 \end{pmatrix}$$

$$Rw' = \left(\frac{Rw}{255} \right)^{1/\gamma} \quad Gw' = \left(\frac{Gw}{255} \right)^{1/\gamma} \quad Bw' = \left(\frac{Bw}{255} \right)^{1/\gamma}$$